


Totley Bridleway repairs

The condition of the public bridleway on Totley Moor that joins Moss road to Stony Ridge road has deteriorated over the last few years. The table below shows the proposed works to repair the wet, muddy sections of the track. Over the worst section nearest the road (section 1), the plan is to have a 1m wide surface of stone that will grass over in time 40mm – 20mm gritstone topped with 20mm-dust gritstone will be used to surface the track. On section 2 stone will be used to fill ruts and puddles to maintain the grassy nature of the track.

| Section No. (see figure 1) | Grid reference | Length of section (m) | Current condition | Desired outcome and action | Resources |
|----------------------------|----------------------------------|-----------------------|-------------------------------------------------------------------------------------|--------------------------------------------|-----------------------------------------------------------------------------------|
| 1 | 427360, 380190 to 427460, 380160 | 100m |  | Surface of track free from mud and puddles | 40 tonnes of 40mm – 20mm gritstone/ 20mm – dust gritstone over section 1 and 2 |



| | | | | | |
|---|-------------------------------------------|-----|-----------------------------------------------------------------------------------|-----------------------------------------------|--------------------------------------------------------------------------------------------|
| 2 | 428139, 379397 to 428065, 379444 | 10m |  | Surface of track free from mud and puddles | 40 tonnes of 40mm – 20mm gritstone/ 20mm – dust gritstone over section 1 and 2 |
|---|-------------------------------------------|-----|-----------------------------------------------------------------------------------|-----------------------------------------------|--------------------------------------------------------------------------------------------|

Figure 1: Location

